SITE NUMBER: WA-II-951
ADDRESS: Across from 50 St. Paul Street, Boonsboro, Maryland
OWNER/LOT NUMBER/ACCESS: private
BUILDING DATE: mid 19th century? pre-1877

This is an east-facing, horizontally massed, one-and-a-half-story, six-bay, frame, freestanding, double house that has been gutted by fire. The building is at the public-right-of-way and is covered with manufactured siding. The tin, side-gable roof has two chimneys and has been extensively damaged. All openings have been boarded up.

Two nearly adjoining buildings are indicated on the 1877 map of the town at this location. The 1897 Sanborn map indicates that they have been joined into a single dwelling. This is confirmed by the roof configuration that is now visible due to the fire damage. The building is numbered 156 on the Sanborns and had an open porch on the rear which has been enclosed since 1940.

The building is within the Western Maryland Geographic Organization, the probable Development Period of Agricultural-Industrial Transition, and falls within the Historic Period Theme of Architecture, Landscape Architecture, and Community Planning.

Prepared by Julianne Mueller, July 1992


P. 559
WA-II-951
BOONSBORO
DETAIL
WA-II-950
P. 483
P. 447
P. 554
P. 603-2
WA-II-961
P. 602
P. 597
P. 598
P. 599
WA-II-977
P. 734
ORCHARD
AVENUE
FORD
LAKIN
STREET
ST. PAUL STREET
DRIVE
CEMETERY
MAIN ST.

WA-II-951
47 St. Paul Street (Across from 50 St. Paul Street)
Sanborn Maps



WA-II-951
47 St. Paul Street, Boonsboro, site (demolished c. 2002)
Funkstown quadrangle



1993-94 Aerial Photo

Tax Map 601, p. 581

WA-II-951
ACROSS FROM 50 ST. PAUL ST, BOONSBORO, WASH. CO.
12.91
JULIE MUELLER.
LOOKING NW